

- BE ACCOMPLISHED.
- A CRITICAL CONNECTOR, ITEM 1B REF B, IS NOT ON HAND .-THIS IS NEEDED TO FABRICATE THE HARNESS WHICH IS REQUIRED FOR BENCH TESTING. THUS, NO TRAINING CAN BE DONE WITH OSCAR SIERRA MK III. 25X1A2g
- SYSTEM 21 SERVICE BULLETIN FOR WILL NOT BE INSTALLED UNTIL SOMETIME IN JANUARY 1968-
- O/S MK III S/B WILL NOT BE INSTALLED BEFORE RECEIPT OF THE ANTENNA, PARA IA REF A. DELIVERY IS UNKNOWN.

Approved For Release 2000/08/24: CIA-RDP71B00263R000100130026-7

25X1A6c

IN 77191

8099

PAGE 2

- 5. ADEQUATE AND PROPER TRAINING ON SYSTEM 21 AND ON OSCAR SIERRA MK III CAN ONLY BE ACCOMPLISHED WHEN THE SYSTEMS ARE AVAILABLE, AND WORKING, IN THE FIELD. 25X1A5a2
- 6. ON THE BASIS OF ABOVE, IT IS RECOMMENDED THAT

 25X1A5a2

 RETURN TO CONUS FOLLOWING THE TEST FLIGHT OF SYSTEM

 17 ON 6 DEC.
 - 7. TECH REP TRAINING ON THESE SYSTEMS CAN BE SCHEDULED WHEN THE EQUIPMENT IS AVAILABLE.

G G G B T TOR: 010403Z DEC 67